

## Tidel Error Messages

Citywide ATM is in no way liable for the misinterpretation of the error codes herewithin, nor are we responsible for hardware that is ordered to fix a machine problem, without direct consultation with a certified Citywide ATM Technician.

### Application Flash Error

- 1) Usually occurs after software download.
- 2) Save setup to floppy and perform a New System Startup in the Program Menu or perform a cold start (J9 jumper)

### Bad Floppy

- 1) Insure write protect tab is off.
- 2) Replace disk with a high density disk & perform Initialize Floppy
- 3) Perform